At the May 27, 198. Toxic Substance Control Commi_ on Meeting the Commission unanimously passed the following motion regarding the Southeast Dakland County Incinerator Authority Landfill (SOCIA).

- Ask SOCIA management to explain the presence of pumps and hoses that lead to the gully which empties into Honeywell Stream.
- 2. Ask DNR to set up a monitoring plan to prevent (a) pumping of leachate into Honeywell Stream and (b) dumping of industrial wastes at the site.
- Ask DNR to monitor any changes at the site to assure a reduction of odor.
- 4. If the revised compliance program proves inadequate to reduce odors, require installation of an exhaust and ventilation system.
- Require buildup of the Mason Farm on Dequindre Road to prevent further leachate flow into Honeywell Stream.
- 6. Request records on chemical evaluation of liquids from monitoring wells.
- 7. Request analysis of <u>leachate</u> being generated now.
- 8. Request <u>permeability data</u> of final cover on cell one. Does it meet Act 641 requirements?
- 9. Request ambient <u>air quality monitoring</u> as in the May 18, 1982 <u>proposed</u> compliance schedule.

US EPA RECORDS CENTER REGION 5